

Akkrediteringens omfattning /Scope of accreditation**Kalibreringsgaser /Calibration gases**

AGA Gas AB, Specialty Gases, Enköping, 5396

Parameter <i>Parameter</i>	Metod (Referens) <i>Method (Reference)</i>	Mätprincip <i>Principle for Measurement</i>	Provtyp <i>Sample type</i>	Bästamätförmåga(±) <i>Best measurement capability (±)</i>	Mätområde <i>Range</i>
Svaveldioxid, SO ₂ <i>Sulfur dioxide, SO₂</i>	SE-16-0741 ISO 6143	UV-fluorescens <i>UV fluorescene</i>	Kvävgas <i>Nitrogen</i>	1,0 %	100-500 ppm
Kvävemonoxid, NO <i>Nitrogen monoxide, NO</i>	SE-16-0742 ISO 6143	Kemiluminiscens <i>Chemiluminiscense</i>	Kvävgas <i>Nitrogen</i>	1,0 %	10-100 ppm
Kvävemonoxid, NO <i>Nitrogen monoxide, NO</i>	SE-16-0743 ISO 6143	Kemiluminiscens <i>Chemiluminiscense</i>	Kvävgas <i>Nitrogen</i>	1,0 %	100-1000 ppm
Kväveoxider, NOx <i>Nitrogen oxides, NOx</i>	SE-16-0742 ISO 6143	Kemiluminiscens <i>Chemiluminiscense</i>	Kvävgas <i>Nitrogen</i>	1,0 %	10-100 ppm
Kväveoxider, NOx <i>Nitrogen oxides, NOx</i>	SE-16-0743 ISO 6143	Kemiluminiscens <i>Chemiluminiscense</i>	Kvävgas <i>Nitrogen</i>	1,0 %	100-1000 ppm
Dikväveoxid (lustgas), N ₂ O <i>Nitrous oxide, N₂O</i>	SE-16-1860 ISO 6143	GC-TCD	Kvävgas <i>Nitrogen</i>	1,0%	10-800 ppm
Syrgas, O ₂ <i>Oxygen, O₂</i>	SE-16-0220 ISO 6143	Paramagnetism <i>Paramagnetic</i>	Kvävgas <i>Nitrogen</i>	1,0 %	2-25 %
Koldioxid, CO ₂ <i>Carbon dioxide, CO₂</i>	SE-16-0352 ISO 6143	NDIR	Kvävgas/luft <i>Nitrogen/air</i>	1,0 %	2-20 %
Kolmonoxid, CO <i>Carbon monoxide, CO</i>	SE-16-0829 ISO 6143	GC-TCD	Kvävgas/luft <i>Nitrogen/air</i>	1,0 %	0,01-1 %
Kolmonoxid, CO <i>Carbon monoxide, CO</i>	SE-16-1862 ISO 6143	GC-FID Methanizer	Kvävgas/luft <i>Nitrogen/air</i>	1,0%	0,001-1 %
Kolmonoxid, CO <i>Carbon monoxide, CO</i>	SE-16-0740 ISO 6143, mod	GC-TCD	Kvävgas <i>Nitrogen</i>	1,0 %	0,5-10 %
Koldioxid, CO ₂ <i>Carbon dioxide, CO₂</i>	SE-16-0740 ISO 6143, mod	GC-TCD	Kvävgas <i>Nitrogen</i>	1,0 %	4 -17 %
Propan <i>Propane, C₃H₈</i>	SE-16-0740 ISO 6143, mod	GC-FID	Kvävgas <i>Nitrogen</i>	1,0 %	100 -5000 ppm

Förändringar märkta med fet stil/Changes are marked with bold style

Bästa mätförmåga (Best measurement capability)

Den bästa mätförmågan är den lägsta mätsäkerhet kalibreringslaboratoriet kan leverera under ideala förhållanden. Den rapporterade osäkerheten är en utvidgad osäkerhet beräknad med täckningsfaktor lika med 2 vilket ger en konfidensnivå på ungefär 95%. Beräkningarna följer dokumentet "Expression of the Uncertainty of Measurement in Calibration" EA4/02

The best measurement capability is the lowest uncertainty allowed reporting on calibration certificate under ideal conditions. The stated expanded uncertainty was obtained by multiplying the combined standard uncertainty u_c with a coverage factor k equal to 2. This corresponds approximately to a 95% confidence interval. The calculations follow the rules in the document "Expression of the Uncertainty of Measurement in Calibration" EA4/02

Verksamhet utanför de egna laboratorielokalerna, s.k. fältverksamhet, ingår inte i ackrediteringen.

Activities outside the laboratory's own premises, so-called field activities, are not included in the accreditation.